User

Wednesday, 4/19/2006 7:42:22 AM

Linda Lacelle

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

: BASKET BASE ASSEMBLY (350)

Job Number

: 26719A

**Estimate Number** : 10189

: NIA P.O. Number This Issue

: 4/19/2006

**Part Number Drawing Number**  : D2221

Prsht Rev.

**Project Number** 

**Drawing Name** 

: D2221/D2235

: NC First Issue

: MA

: LARGE FAB ASSY Type

**Drawing Revision** 

: N/A : F/B1

**Previous Run** 

: 26718A

Material

: NIA

1 Um:

Written By

:SER COMMENT BELOW AROVE USER & NATE.

**Due Date** 

: 4/30/2006

Qty:

Each

**Checked & Approved By** 

Comment

: Est Rev:J 05.09.02 Added D3442-1KJ/JLM

**Additional Product** 

Job Number:



Sea. #:

**Machine Or Operation:** 

Description:

D31661 1.0

Basket Hoop



Comment: Qty.:

4.0000 Each(s)/Unit Total:

4.0000 Each(s)

Pick:

**Qty Part Number** 4 D3166-1

Description Batch

CPC 06-04-19

2.0

D22323

2.0000 Each(s)

Pick:

Comment: Qty.:

**Qty Part Number** 

Description Batch

Total:

2 D2232-3

2.0000 Each(s)/Unit

Hinge bracket 452523

06-04-26

3.0

D2325

Support Gusset (350 Basi





4.0000 Each(s)/Unit Total:

4.0000 Each(s)



Comment: Qty.:

Pick: **Qty Part Number** 

Description

4 D2325

Support Gusset

CAL06.04.26

4.0

D23273

Spacer Bushing





2 D2327-3

Comment: Qty.:

2.0000 Each(s)/Unit

Bushing

Total: 2.0000 Each(s)

Pick:

**Qty Part Number** 

Description

CPC 06.04.20

Dart Ae	rospace l	Ltd							
<b>W</b> /O:		The state of the s	WO	RK ORDER CHANGES	)			7	
DATE	STEP	PROC	GE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		ŧ							
Part No		PAR #:	Fault Catego	ory: N	ICR: Yes	No DQA	\: <u> </u>	_ Date: _	
								_ Date: _	
NCR:		W	ORK ORDE	R NON-CONFORMANO	CE (NCR	)			
DATE	STEP	Description of NC Section A	Corrective Action Section			Verific	ication	Approval	Approval
DATE			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
	7		2.						
				×.					
							;		:

NOTE: Date & initial all entries

Date: Wednesday, 4/19/2006 7:42:22 AM User: Linda Lacelle **Process Sheet** Drawing Name: BASKET BASE ASSEMBLY (350) Customer: CU-DAR001 Dart Helicopters Services Job Number: 26719A Part Number: D2221 Job Number: Seq. #: **Machine Or Operation:** Description: 5.0 D2581 Mounting Bracket Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Pick: **Qty Part Number** Description CAC 06.04.26 2 D2581 Mounting Bracket D34421 6.0 2.0000 Each(s) Comment: Qty.: 2.0000 Each(s)/Unit Total: **Qty Part Number** Description 2 D3442-1 Shim CPL 06.04.26 M304EX07516F 7.0 **Expanded Metal Flat Stai** Comment: Qty.: 39.6900 sf(s)/Unit Total: 39.6900 sf(s) Pick: **Qty Part Number** Description Batch CPL06.04-25 36 sf M304EX0.75-16F Expanded Metal M304TS0750W065 8.0 Comment: Qty.: 29.4000 f(s)/Unit Total: 29.4000 f(s) Pick: 28' 3/4" x 3/4" x 0.063 wall 304/316 SStubing Batch:  $M100704 \longrightarrow 336/0/$ CRO6-04-19 LARGE FAB 1 9.0 LARGE FABRICATION RESOURCE 1 **Comment: LARGE FABRICATION RESOURCE 1** CPL 06.04.27 1-Cut D2235-1 Rib from D3166-1 Rib As Per Dwg D2235 2-Drill hole in D2221-3 as per Dwg D2221 3-Deburr 4-Remove all markings on material before welding 5-Weld as per Dwg D2221 using Welding Table and corner JigDeburr as required Page 2 Form: rprocess

## **Dart Aerospace Ltd**

,	. oopao.	, E.u.	7							
W/O:	1.00		W	ORK ORDER C	HANGES		4			
DATE	STEP	PROC	OCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			L.							
		#***					***************************************			
				÷ ·						
Part No	:	PAR #:	_ Fault Cate	gory:	NO	CR: Yes (	No DQ	A: 5	Date: ≥	2/05/0
						QA: N	C Close	d:	_ Date: _	÷
NCR:		W	ORK ORD	ER NON-CON	FORMANC	E (NCR	)			
DATE	STEP	Description of NC	Corrective Action Section B				Verific	ation	Approval Chief Eng	Approval QC Inspector
DAIL	SIEF	Section A	Initial Chief Eng			n Sign & Date		on C		
					4.					
ž.										
	4									
	(4-)	(\$)								
er eg										

NOTE: Date & initial all entries

Date: Wednesday, 4/19/2006 7:42:22 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BASKET BASE ASSEMBLY (350) Job Number: 26719A Part Number: D2221 Job Number: Seq. #: **Machine Or Operation: Description:** 10.0 QC9/6 DDIMENSIONAL & WELDING INSPECTION Comment: DDIMENSIONAL . & WELDING INSPECTION 11.0 POWDER COATING **Comment: POWDER COATING** Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 12.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 13.0 HAND FINISHING RESOURCE #1 Comment: HAND F INISHING RESOURCE #1 Seal support gusset seam with white sikaflex-291 Batch: MIGOY 80 Expiry date: \_ 11 2000 14.0 DOCUMENT CONTROL Comment: DOCUMENT CONTROL Inspection Level 21

Job Completion



L 06.05.03

## **Dart Aerospace Ltd**

DaitAc	·ospaot	Ltu								
W/O:			W	ORK ORDER CH	ANGES					
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			e <sup>2</sup>							
		•	- C							
Part No	:	PAR #:	Fault Cate	gory:	NC	R: Yes N	lo <b>DQ</b> A	<b>\</b> :	Date:	
						QA: N/	C Closed	d:	_ Date: _	·
NCR:			WORK ORD	ER NON-CONFO	PRMANCE	(NCR)				
	STEP	Description of NC Section A	Corrective Action Section B			Varifi		cation	Approval	Approval
DATE			Initial Chief Eng	Action Descrip Chief Eng	otion	Sign & Date	Section C		Chief Eng	QC Inspector
		4								
							100			

NOTE: Date & initial all entries